Timber Newsletter Index

150x150

Feedback on 150x150 - January 2015

The drought uncovers some deadly sins - March 2020

Which hardwood grading standard should I use – April 2020

3D Printing

Introduction to 3D printing - February 2015

50 mm joists

A reminder - February 2015

Deadly Sin No. 2 on the sunshine Coast-April 2019

Stagger your screw line - July 2019

Correct detailing does matter - November 2020

Battens

Simple but stunning use of battens – June 2019

What has a Big Mac and cladding have in common – December 2019

Fastener end distances - November 2023

Don't span your battens too far - February 2024

Boardwalks

Sacred site Boardwalks - April 2015

Why do I bother - June 2015

The Customer isn't always right – November 2017

Lessons from a 30-year-old boardwalk - December 2017

A boardwalk that planned to succeed-March 2019

Please explain - December 2019

Correct detailing does matter - November 2020

Galvanised fasteners can be a Recipe for Disaster – November 2021

We can be too clever (flood resilience) - March 2022

Bollards

Bollards – Let the buyer beware – October 2015

Canberra bollards- January 2015

Same plans but two different products – <u>December 2015</u>

Timber bollards that have not aged gracefully – May 2015

Attractive project using eclipse bollards - September 2018

FWPA bollard guide - October 2018

Don't specify bollards till you read this guide - November 2018

Spreading the word in Canberra - May 2019

How deep do bollards have to be in the ground – October 2019

New CPD course on bollards - March 2023

Why do we do things that are just plain wrong - April 2023

Plastic or timber bollards, which is better? - October 2023

Books

Architectural Timber Batten Book completed - August 2015

Baptist History - February 2015

Fence images sought - September 2015

Help needed for architectural battens - May 2015

Images sought for footbridge book – August 2015

New book being written (Architectural Timber Battens) – June 2015

New publication finalised – October 2015, – February 2016

New book on joints being written – May 2016

Contribution to French book on tropical timber – June 2016

New book on timber joints - March 2017

New guide, External Timber Furniture - September 2018

A treat for wood lovers and railway buffs – September 2020

Pre-release editions of Timber in Playgrounds available – March 2021

Why you need Bootle's Wood in Australia – July 2022

Guide to timber handrail released – <u>December 2022</u>

Started new guide to timber steps - March 2023

Restoring a bridge for 1/10th the cost of concrete – April 2023

You need the industry "Bible" - July 2023

Bridges

Bridge inspection course - January 2015

Log Footbridges - April 2015

Large timber structures - April 2015 special edition

Paint finish for external structures – June 2015

Wisdom of high design loads - May 2015

New publication being finalised – September 2015

What does a London bus have in common with my trusses?— December 2015

Large Timber structures – April 2016 special edition

Covered bridges and the birth of American engineering-November 2016

Mareeba Shire turns to timber bridges over concrete - August 2017

You can build an Oscar worthy bridge – January 2018

Economic and speedy bridge replacement – July 2018

Covered bridges really work - April 2019

Pre-war but which war (40m timber bridge) January 2020

Krause bridge, a lesson in longevity – May 2020

The capabilities of external gluelam – August 2020

Another timber bridge to replace steel in Canada – October 2020

Iconic timber bridge restored (Brunswick Heads) – December 2020

Covered bridge restoration – February 2021

An Interesting handrail from the UK (sloping handrails) - July 2021

A Not so interesting handrail from Australia (poorly done) – July 2021

Poor Timber Design Needed a Fast Repair (laminated beam) – August 2021

35 metre span timber bridge in Canada – February 2022

A problematic timber design – August 2022

Buildings

Another great project from architects of Arcadia – June 2020

Another one of my follies – October 2020

Inspecting the world's largest timber structure – January 2024

Case Histories - Bad

Dangerous Canberra Deck - January 2015

Dangerous Canberra deck finally made safe – <u>January 2017</u>

Why do I bother (Re boardwalk) - June 2015

Timber bollards that have not aged gracefully – May 2015

Problematic timber bridge design – August 2022

Step case history from step guide – May 2023

A creative footing solution – February 2024

Case Histories - Good

Largest timber church in Australia – June 2016

Salt storage shed East Windsor (USA) using shearplates – February 2017

A decent garden wall – March 2017

Rothoblass headquarters Italy using cross laminated timber – March 2017

Tree of Knowledge memorial Barcaldine – April 2017

Mareeba Shire turns to timber bridges over concrete - August 2017

Kurata Co in Japan excels with spotted gum – April 2018

An early boardwalk revisited (Toohey Forest) - May 2018

Another great structure at Toohey Forest Park, Part 1– June 2018

Another great structure at Toohey Forest Park, Part 2- July 2018

Are you purchasing for durability (Brisbane Botanic Garden) - October 2018

Another one of my follies (bell tower Dalby) - November 2020

Domestic deck at The Gap - February 2021

Ports North Playground – Cairns – March 2021

Spotted gum seats in Budapest - May 2021

Queenslander houses – May 2021

Deck replacement – Gold Coast – October 2021

Two bell towers compared (Dalby and Charters Towers) – November 2021

We can be too clever (flood resilience) - March 2022

Spotted gum viewing deck in Japan – June 2022

Something good in Canberra (pergola) – August 2022

Refurbished deck at Samford – <u>December 2022</u>

All Hallows school deck – May 2023

Uluru drone show boardwalk and deck – June 2023

Amazing spotted gum deck in Japan – August 2023

Handrail on refurbished footbridge – October 2023

Sunpu's workshop, Takumijuku (Japan) – December 2023

Cladding

What have a Big Mac and cladding have in common – December 2019

Whoever thought plastic was a good idea – September 2019

Timber cladding in multi-story buildings – <u>September 2020</u>

Cocowood

Cocowood, is it any good? - October 2016

Connections

World's largest timber structure - March 2016

Salt storage shed East Windsor (USA) using shearplates – February 2017

Consultancy Services

Expert witness - November 2015

Ted is speaking on battens for Timber Queensland – January 2016

Gold Coast City Council builds an outstanding deck - July 2017

Consultancy services through BCRC - August 2017

The importance of Timber Grading – December 2017

Footbridge inspections - August 2018

Grading timber in a Venetian palace – November 2018

Why you need to engage a timber consultant even if it's not me – November 2019

Cypress

The difference between pine hardwood and cypress – September 2016

Deck Collapses

Another deck collapse - December 2017

Another deck fatality before the coroner – June 2020

Decks - Commercial

Deckwood – new manufacturing arrangements – January 2016

Ted has finally found something more durable than Deckwood – November 2015

Width to thickness ratio - - November 2016

How long will a timber deck last - March 2017

Joining decks on commercial decking - June 2017

Choosing timber by colour - July 2017

Gold Coast City Council builds an outstanding deck – July 2017

What decking profile us that - July 2017

Should decks be load limited – November 2017

It is a good idea to pre-oil your deck – November 2017

Avoiding trip hazards in decking - April 2020

Are your decks self-cleaning - April 2020

Why you don't use dressed face decking externally - August 2018

Putting form before function - June 2019

Spotted gum decks in Japan - May 2020

This is why you do things correctly – July 2020

Japanese tea garden deck – July 2020

Why don't we check - August 2020

Deck replacement - Gold Coast - October 2021

What decking oil should I use – May 2022

Deckwood available for vehicle decking – June 2022

Amazing spotted gum deck in Japan – August 2023

Decks - Domestic

How to ensure correct verandah joist life – August 2015

Nail or screw domestic decking – April 2015

Some basics – November 2015

How to Protect and keep your deck looking good – June 2017

Choosing timber by colour - July 2017

Should decks be load limited – November 2017

It is a good idea to pre-oil your deck – November 2017

Why you don't use dressed face decking externally - August 2018

A Dear Lord Give my strength moment – January 2019

Updated Timber Queensland Decking Guides - September 2019

LVL and common sense (USA deck collapse) – February 2020

Spotted gum decks in Japan - May 2020

Another deck fatality before the coroner – June 2020

Beware F17 KD specification – September 2021

What decking oil should I use - May 2022

Refurbished deck at Samford (LifePlus) - December 2022

All hallows School Lifeplus – May 2023

Timber decks close to the ground – <u>December 2023</u>

Decks - Plastic

Plastic decking with termites - September 2016

It seemed a good idea at the time – August 2017

Another failed plastic deck - April 2018

Timber, is there a better product – May 2019

Whoever thought plastic was a good idea – September 2019

Durability

Thermally modified timber - <u>January 2015</u>

Designing for the local climate – November 2015

Non durable timber has lasted more than 100 years – May 2016

Deadly Sin No. 7, Getting Durability ratings Right - February 2019

Oils ain't oils and wood ain't wood – February 2019

National centre for timber durability – June 2020

This is why I disapprove of using Oregon pine externally – July 2020

A quick look at some common species - October 2020

Another one of my follies (Kangaroo Point) - October 2020

Another one of my follies (Bell tower Dalby) – November 2020

Beware F17 KD specification – September 2021

Two bell towers compared (Dalby and Charters Towers) - November 2021

We can be too clever (flood resilience) - March 2022

Is Oregon durable - May 2023

Care needed with kwila/merbau – November 2023

Engineered Timber

Using laminated beams externally – September 2015

Using LVL beams externally – September 2015

Rothoblass headquarters Italy using cross laminated timber - March 2017

Timber library in remote Solomon Islands – May 2017

Mareeba Shire turns to timber bridges over concrete - August 2017

Be careful choosing your species - October 2017

Fences - Domestic

Fence images sought – September 2015, October 2015

Timber fence book finalised – January 2016

Everything fencing - April 2016

Be careful with ply fences - September 2017

Be careful choosing your species - October 2017

A striking spotted gum fence in Japan – March 2021

How not to do a fence - April 2022

Horse fencing - November 2023

Fasteners

Nail or screw domestic decking – April 2015

When to use stainless bolts and brackets – July 2015

Galvanised bolts more variable than timber - June 2016

Problems looming with self drilling screws – <u>June 2016</u>

More on galvanised bolts – July 2016

More on galvanised bolts - August 2016

More on galvanised bolts – September 2016

Choosing the correct decking fastener part 1 – November 2016

Choosing the correct decking fastener part 2 – <u>December 2016</u>

Choosing the correct decking fastener part 3 – January 2017

Corroding galvanised joist hangers - November 2016

Tube nuts - December 2016

Salt storage shed East Windsor (USA) using shearplates – February 2017

A Dear Lord Give my strength moment - January 2019

Stagger your screw line - July 2019

Why don't we check - August 2020

Vandal resistant fasteners – February 2021

Tell me how to detail it Correctly (steel corroding at stainless bolt) - April 2021

Tell me how to detail it Correctly replies (steel corroding at stainless bolt) – June 2021

Staying one jump ahead of the idiots (need for special nuts) – June 2021

Galvanised fasteners can be a Recipe for Disaster – November 2021

End and edge clearances of bolts - March 2022

Fastening domestic decking to steel joists – February 2023

Recommended screw for fixing Deckwood to steel – August 2023

Fastener end distances - November 2023

Flooring

A real-life ghost story – March 2015

Controlling the gaps in T&G flooring – March 2018

When is kiln dried not kiln dried – January 2019

A reminder about narrow floorboards – September 2019

Queenslander houses - May 2021

Using T&G flooring as decking – February 2023

Finishing

A real-life ghost story - March 2015

Paint finish for external structures – June 2015

Keep Your Deck Looking Good & Protected – June 2017

It is a good idea to pre-oil your deck - November 2017

Don't do silly things with timber - November 2019

Choice of paint colour is important – <u>December 2020</u>

Tell me how to detail it correctly replies (painted steel corroding at stainless bolt) - June 2021

What decking oil should I use – May 2022

Fire

Fire retardant coatings code of practice released - June 2018

A lesson from the recent bushfires (CCA and fire) - January 2020

Feedback on a lesson from recent bushfires – February 2020

Furniture

Be careful choosing your species – October 2017

Writing a book on external furniture – November 2017

External timber furniture, all you need to know – October 2018

Grading

A reminder about sleepers - March 2016

How to measure end splits – March 2016

Limitations of visual grading – January 2018

Don't specify timber by F grades – August 2018

Which hardwood grading standard should I use - April 2020

A philosophical question prompted by Kortney and Dave – January 2021

Losing confidence in timber is so unnecessary – September 2021

Beware F17 KD specification – September 2021

Deck replacement – Gold Coast – October 2021

How not to do a fence - April 2022

New hardwood requires care in its specification – June 2022

Guide to timber handrail released – <u>December 2022</u>

Never specify sleepers – <u>June 2023</u>

A broken heart in one so young - August 2023

Handrail

Detailing a commercial handrail – June 2019

An Interesting handrail from the UK (sloping handrails) - July 2021

A Not so interesting handrail from Australia (poorly done) – July 2021

New CPD Course on handrail - August 2021

Losing confidence in timber is so unnecessary – September 2021

Fixing handrails - October 2021

Correct use of LOSP Treated Handrail - January 2022

Do end sealants actually work – February 2022

A suggested handrail bracket - February 2022

Specification for commercial handrail – July 2022

Guide to timber handrail released – <u>December 2022</u>

Handrail on refurbished footbridge - October 2023

Hardware

Fencing brackets - February 2016

Corroding galvanised joist hangers - November 2016

Salt storage shed East Windsor (USA) using shearplates – February 2017

Stump caps - March 2017

Heart in timber

Feedback on 150x150- January 2015

The difference between pine hardwood and cypress – September 2016

Using heart-in timber – February 2017

Stump caps – March 2017

Tree of Knowledge memorial Barcaldine – April 2017

Using heart in timber correctly – April 2020

Losing confidence in timber is so unnecessary – September 2021

History

The two Henry Fords of housing (part 1) - August 2016

The two Henry Fords of housing (part 2) – September 2016

Trusses a brief history – October 2016

Largest timber gable truss in Australia - December 2016

Sons of Gwalia headframe restoration options - April 2017

Incised timber

Incised Timber - November 2020

Feedback on incised timber - <u>December 2020</u>

Feedback on Recognising well treated sleepers – February 2024

International

Brief trip to the Philippines – September 2016

Cocowood, is it any good? - October 2016

Rothoblass headquarters Italy using cross laminated timber – March 2017

Timber library in remote Solomon Islands – May 2017

Cyclone and earthquake resistant building in Solomons – October 2018

Spotted gum decks in Japan – May 2020

Japanese tea garden deck - July 2020

Spotted gum projects in Japan – September 2020

Spotted gum viewing deck in Japan – June 2022

Amazing spotted gum deck in Japan – August 2023

Joints

Tamedia building in Switzerland - May 2016

Galvanised bolts more variable than timber – <u>June 2016</u>

Problems looming with self-drilling screws – June 2016

Tamedia building, Zurich - August 2016

Joists

Predrilling joists for screws is critical – February 2018

How not to do a timber joint – August 2018

A reminder about steel joists – November 2018

This may make steel joists work – December 2018

You can Make Steel Joists Work - January 2019

Deadly Sin No. 2 on the sunshine Coast-April 2019

Don't do silly things joining timber – October 2019

Correct detailing does matter - November 2020

Beware F17 KD specification – September 2021

Fastening domestic decking to steel joists - February 2023

Laminated timber

Pre-war but which war (40m laminated timber bridge) January 2020

Don't do silly things with laminated timber – October 2019

Poor Timber Design Needed a Fast Repair (laminated beam bridge) - August 2021

LVL

LVL and common sense (USA deck collapse) - February 2020

Moisture Content

UTAS Want Your Moisture Content Story – December 2020

Paint and Oils

What brand paint should I use – <u>July 2016</u>

Lui the wood turner is a fan of Tanacoat – October 2016

Keep Your Deck Looking Good & Protected – June 2017

It is a good idea to pre-oil your deck – November 2017

Choice of paint colour is important – <u>December 2020</u>

What paint brand should I specify - April 2022

What decking oil should I use - May 2022

Tanacoat or Tanacare - February 2024

Pests of timber

Identifying lyctus attack - January 2018

Pine

The difference between pine hardwood and cypress – September 2016

Never purchase treated pine on price – August 2019

Is Oregon durable – May 2023

Plastic Decking

See decking - Plastic

Timber, is there a better product – May 2019

Whoever thought plastic was a good idea – September 2019

Playgrounds

Kim Bowman Music – June 2017

Rethinking Robinia playground equipment – <u>December 2018</u>

Use of Larch in Australia - May 2019

Wishful thinking verse planning to succeed – July 2019

The perils of reverse engineering – <u>December 2019</u>

Most skilled spotted gum project I have ever seen – July 2020

Only trust your mother – August 2020

Playground timber – progress and request for images - November 2020

Timber in playgrounds (Broadwater project) - January 2021

Vandal resistant fasteners - February 2021

Ports North Playground – Cairns – March 2021

Pre-release editions of Timber in Playgrounds available – March 2021

Text finalised for Timber in Playground guide – June 2021

Example of why you need the playground guide - January 2022

Bradbury Park Playspace - July 2023

Plywood

Be careful with ply fences – <u>September 2017</u>

New book on plywood – October 2017

Posts

Hardwood posts in concrete – February 2016

Lui the wood turner is a fan of Tanacoat (turned posts) – October 2016

Stump caps - March 2017

How not to install a post – April 2017

Something else that seemed a good idea – August 2017

Your design sins will find you out, Part 1– May 2018

Your design sins will find you out, Part 1- June 2018

Deadly Sin No 6 at Jimna Fire Tower - March 2019

A lesson from the recent bushfires - January 2020

Feedback on a lesson from recent bushfires – February 2020

The drought uncovers some deadly sins – March 2020

Lay your design sins at the foot of the cross (revisited) - June 2021

Basic error with post supports - January 2022

Why do we do things that are just plain wrong – April 2023

Guidelines for installing gal posts in concrete - April 2023

Groundline special edition – September 2023

Post size requirements – September 2023

Timber house stumps – <u>September 2023</u>

Lay your design sins at the foot of the cross (revisited again) – September 2023

Steel posts – September 2023

A creative footing solution – February 2024

Projects

Tamedia building, Zurich - August 2016

A striking spotted gum fence in Japan – March 2021

Waaje Fire Tower Refurbishment - April 2021

Recycled timber

Recycled timber – Political Correctness – April 2016

Is recycled timber seasoned – October 2017

A good use of recycled timber – February 2020

Sapwood

Considering sapwood in your design - December 2021

Seats

This seat suits all age groups—April 2019
Spotted gum seats in Budapest — May 2021

Shelters

The perils of reverse engineering – <u>December 2019</u> Shelter shed design service – <u>August 2021</u>

Sleepers

A reminder about sleepers – March 2016

Concrete or timber sleepers – July 2016

A decent garden wall – March 2017

Jack has a rant about dodgy treatment – May 2017

Guide to Timber Garden Retaining walls – November 2017

Should have used concrete not timber – August 2019

Never specify sleepers – June 2023

Recognising correctly treated sleepers – January 2024

Feedback on Recognising well treated sleepers – February 2024

Slip resistance

Putting form before function - June 2019

Standards

Standards you can drive a bus through – March 2015
Feedback on deficient standards – June 2015
Forest red gum – something I just noticed – August 2015
Revised standard AS/NZS 1170.2 released - August 2016
A quick look at some common species – October 2020
A Rose by any Other Name Might be Lemon (species names) – April 2021

Steps

Specification for step treads – <u>July 2022</u> Case history (bad) from step guide – <u>May 2023</u>

Sundry

Inspect research Facilities – <u>June 2015</u>
Know a decent door supplier – <u>July 2019</u>
I found a decent door supplier – <u>August 2019</u>
A fair question about purchasing on price – <u>November 2019</u>
A Specification tool that is desperately needed – <u>September 2020</u>
Is spotted gum the cure for covid? (piggery slats) – <u>March 2021</u>
Calculating the weight of timber – <u>August 2021</u>
Horse fencing – <u>November 2023</u>

Timber Construction

Where is Timber Construction headed - May 2015

World's largest timber structure - March 2016

Large Timber structures - April 2016 special edition

Large Timber structures follow up - April 2016

Non-durable timber has lasted more than 100 years – May 2016

They are not using shipping containers, are they? – August 2016

Largest timber gable truss in Australia – December 2016

Salt storage shed East Windsor (USA) using shearplates – February 2017

The age of the plyscraper – March 2018

Protect your top surface - May 2018

Another one of my follies – October 2020

Timber Queensland

Report on Feb 2016 Seminar - February 2016

Timber Research

The state of Timber research in Australia – May 2016

The state of Timber research in Australia – June 2016

The state of Timber research in Australia - July 2016

National Centre for Timber durability - November 2018

Timber Structures

World's largest timber structure - March 2016

Large Timber structures - April 2016 special edition

Large Timber structures follow up - April 2016

Non durable timber has lasted more than 100 years - May 2016

Treatment

Decay in treated pine - December 2015

Decay in treated pine - January 2016

Why so hard to do the right thing - - January 2016

Jack has a rant about dodgy treatment – May 2017

When is H3 not H3? May 2017

A reminder about pine – July 2017

Cairns Regional Council sets the standard for preservation – September 2017

How to confirm correct treatment has been achieved – <u>December 2017</u>

Timber treatments do not repel insects – February 2018

Timber, is there a better product – May 2019

Guide for exercising due diligence with treated timber – November 2019

Lesson from a recent bushfire (CCA and fire) – January 2020

LVL and common sense - February 2020

Another one of my follies (Bell tower Dalby) – November 2020

Update to new timber preservation guide for free – January 2021

Considering sapwood in your design - <u>December 2021</u>

Correct use of LOSP Treated Handrail - January 2022

What do the numbers on a treatment tag mean? - January 2024

Unclasifiable

A mortgage broker that helped us – February 2016

How to get people to specify your product – February 2016

What do you do with a good idea - February 2016

An accountant that really helped us - May 2016

Sons of Gwalia headframe restoration options - April 2017

Book on the history of saws – February 2017

A treat for wood lovers and railway buffs – September 2020

Is spotted gum the cure for covid? (piggery slats) – March 2021

The Olympics of materials – July 2021

Design decision making matrix is needed – August 2022

Glad to help a young engineer with her master's degree - March 2023

Something for lovers of concrete - March 2023

Verandahs

See Decks Domestic

Wood Solutions

New guide on mid rise developments released – October 2016

Span chart software – February 2017

Guide to Timber Garden Retaining walls – November 2017

New publication on slip resistance – <u>December 2018</u>

Guide to Wood Construction Systems – <u>January 2019</u>

Wood Encouragement Policy

A wood encouragement policy is a mixed blessing - August 2017

A wood encouragement policy, what is needed-August 2017