

Timber Newsletter Index

150x150

Feedback on 150x150 - January 2015
The drought uncovers some deadly sins – March 2020
Which hardwood grading standard should I use – April 2020

3D Printing

Introduction to 3D printing – February 2015

50 mm joists

A reminder - February 2015
Deadly Sin No. 2 on the sunshine Coast– April 2019
Stagger your screw line – July 2019
Correct detailing does matter - November 2020

Battens

Simple but stunning use of battens – June 2019
What has a Big Mac and cladding have in common – December 2019

Boardwalks

Sacred site Boardwalks – April 2015
Why do I bother – June 2015
The Customer isn't always right – November 2017
Lessons from a 30-year-old boardwalk – December 2017
A boardwalk that planned to succeed– March 2019
Please explain – December 2019
Correct detailing does matter - November 2020

Bollards

Bollards – Let the buyer beware – October 2015
Canberra bollards- January 2015
Same plans but two different products –December 2015
Timber bollards that have not aged gracefully – May 2015
Attractive project using eclipse bollards – September 2018
FWPA bollard guide – October 2018
Don't specify bollards till you read this guide – November 2018
Spreading the word in Canberra – May 2019
How deep do bollards have to be in the ground – October 2019

Books

Architectural Timber Batten Book completed – August 2015
Baptist History - February 2015
Fence images sought – September 2015
Help needed for architectural battens – May 2015
Images sought for footbridge book – August 2015
New book being written (Architectural Timber Battens) – June 2015
New publication finalised – October 2015, – February 2016

New book on joints being written – May 2016
Contribution to French book on tropical timber – June 2016
New book on timber joints – March 2017
New guide, External Timber Furniture – September 2018
A treat for wood lovers and railway buffs – September 2020
Pre-release editions of Timber in Playgrounds available – March 2021

Bridges

Bridge inspection course - January 2015
Log Footbridges – April 2015
Large timber structures – April 2015 special edition
Paint finish for external structures – June 2015
Wisdom of high design loads – May 2015
New publication being finalised – September 2015
What does a London bus have in common with my trusses?– December 2015
Large Timber structures – April 2016 special edition
Covered bridges and the birth of American engineering– November 2016
Mareeba Shire turns to timber bridges over concrete -August 2017
You can build an Oscar worthy bridge – January 2018
Economic and speedy bridge replacement – July 2018
Covered bridges really work – April 2019
Prewar but which war (40m timber bridge) January 2020
Krause bridge, a lesson in longevity – May 2020
The capabilities of external gluelam – August 2020
Another timber bridge to replace steel in Canada – October 2020
Iconic timber bridge restored (Brunswick Heads) – December 2020
Covered bridge Restoration – February 2121

Buildings

Another great project from architects of Arcadia – June 2020
Another one of my follies – October 2020

Case Histories - Bad

Dangerous Canberra Deck - January 2015
Dangerous Canberra deck finally made safe – January 2017
Why do I bother (Re boardwalk) - June 2015
Timber bollards that have not aged gracefully – May 2015

Case Histories - Good

Largest timber church in Australia – June 2016
Salt storage shed East Windsor (USA) using shearplates – February 2017
A decent garden wall – March 2017
Rothoblass headquarters Italy using cross laminated timber – March 2017
Tree of Knowledge memorial Barcaldine – April 2017
Mareeba Shire turns to timber bridges over concrete -August 2017
Kurata Co in Japan excels with spotted gum
An early boardwalk revisited (Toohey Forest) – May 2018
Another great structure at Toohey Forest Park, Part 1– June 2018
Another great structure at Toohey Forest Park, Part 2– July 2018

Are you purchasing for durability (Brisbane Botanic Garden) – October 2018
Another one of my follies (bell tower Dalby) - November 2020
Domestic deck at The Gap - February 2021
Ports North Playground – Cairns – March 2021

Cladding

What have a Big Mac and cladding have in common – December 2019
Whoever thought plastic was a good idea – September 2019
Timber cladding in multi story buildings – September 2020

Cocowood

Cocowood, is it any good? – October 2016

Connections

World’s largest timber structure – March 2016
Salt storage shed East Windsor (USA) using shearplates – February 2017

Consultancy Services

Expert witness – November 2015
Ted is speaking on battens for Timber Queensland – January 2016
Gold Coast City Council builds an outstanding deck – July 2017
Consultancy services through BCRC – August 2017
The importance of Timber Grading – December 2017
Footbridge inspections – August 2018
Grading timber in a Venetian palace – November 2018
Why you need to engage a timber consultant even if it’s not me – November 2019

Cypress

The difference between pine hardwood and cypress – September 2016

Deck Collapses

Another deck collapse – December 2017
Another deck fatality before the coroner – June 2020

Decks – Commercial

Deckwood – new manufacturing arrangements – January 2016
Ted has finally found something more durable than Deckwood – November 2015
Width to thickness ratio - – November 2016
How long will a timber deck last – March 2017
Joining decks on commercial decking – June 2017
Choosing timber by colour - July 2017
Gold Coast City Council builds an outstanding deck – July 2017
What decking profile us that – July 2017
Should decks be load limited – November 2017
It is a good idea to pre-oil your deck – November 2017
Avoiding trip hazards in decking – April 2020
Are your decks self-cleaning – April 2020
Why you don’t use dressed face decking externally – August 2018
Putting form before function – June 2019
Spotted gum decks in Japan – May 2020

This is why you do things correctly – July 2020

Japanese tea garden deck – July 2020

Why don't we check – August 2020

Decks - Domestic

How to ensure correct verandah joist life – August 2015

Nail or screw domestic decking – April 2015

Some basics – November 2015

How to Protect and keep your deck looking good – June 2017

Choosing timber by colour - July 2017

Should decks be load limited – November 2017

It is a good idea to pre-oil your deck – November 2017

Why you don't use dressed face decking externally – August 2018

A Dear Lord Give my strength moment – January 2019

Updated Timber Queensland Decking Guides – September 2019

LVL and common sense (USA deck collapse) – February 2020

Spotted gum decks in Japan – May 2020

Another deck fatality before the coroner – June 2020

Decks - Plastic

Plastic decking with termites – September 2016

It seemed a good idea at the time – August 2017

Another failed plastic deck – April 2018

Timber, is there a better product – May 2019

Whoever thought plastic was a good idea – September 2019

Durability

Thermally modified timber - January 2015

Designing for the local climate – November 2015

Non durable timber has lasted more than 100 years – May 2016

Deadly Sin No. 7, Getting Durability ratings Right – February 2019

Oils ain't oils and wood ain't wood – February 2019

National centre for timber durability – June 2020

This is why I disapprove of using Oregon pine externally – July 2020

A quick look at some common species – October 2020

Another one of my follies (Kangaroo Point) – October 2020

Another one of my follies (Bell tower Dalby) – November 2020

Engineered Timber

Using laminated beams externally – September 2015

Using LVL beams externally – September 2015

Rothoblass headquarters Italy using cross laminated timber – March 2017

Timber library in remote Solomon Islands – May 2017

Mareeba Shire turns to timber bridges over concrete -August 2017

Be careful choosing your species – October 2017

Fences – Domestic

Fence images sought – September 2015, October 2015

Timber fence book finalised – January 2016

Everything fencing – April 2016

Be careful with ply fences – September 2017
Be careful choosing your species – October 2017
A striking spotted gum fence in Japan – March 2121

Fasteners

Nail or screw domestic decking – April 2015
When to use stainless bolts and brackets – July 2015
Galvanised bolts more variable than timber – June 2016
Problems looming with self drilling screws – June 2016
More on galvanised bolts – July 2016
More on galvanised bolts – August 2016
More on galvanised bolts – September 2016
Choosing the correct decking fastener part 1 – November 2016
Choosing the correct decking fastener part 2 – December 2016
Choosing the correct decking fastener part 3 – January 2017
Corroding galvanised joist hangers – November 2016
Tube nuts – December 2016
Salt storage shed East Windsor (USA) using shearplates – February 2017
A Dear Lord Give my strength moment – January 2019
Stagger your screw line – July 2019
Why don't we check – August 2020
Vandal resistant fasteners – February 2121
Tell me how to detail it Correctly – April 2021

Flooring

A real-life ghost story – March 2015
Controlling the gaps in T&G flooring – March 2018
When is kiln dried not kiln dried – January 2019
A reminder about narrow floor boards – September 2019

Finishing

A real-life ghost story – March 2015
Paint finish for external structures – June 2015
Keep Your Deck Looking Good & Protected – June 2017
It is a good idea to pre-oil your deck – November 2017
Don't do silly things with timber – November 2019
Choice of paint colour is important – December 2020

Fire

Fire retardant coatings code of practice released – June 2018
A lesson from the recent bushfires – January 2010
Feedback on a lesson from recent bushfires – February 2020

Furniture

Be careful choosing your species – October 2017
Writing a book on external furniture – November 2017
External timber furniture, all you need to know – October 2018

Grading

A reminder about sleepers – March 2016

How to measure end splits – March 2016
Limitations of visual grading – January 2018
Don't specify timber by F grades – August 2018
Which hardwood grading standard should I use – April 2020
A philosophical question prompted by Kortney and Dave – January 2021

Handrail

Detailing a commercial handrail – June 2019

Hardware

Fencing brackets – February 2016
Corroding galvanised joist hangers – November 2016
Salt storage shed East Windsor (USA) using shearplates – February 2017
Stump caps – March 2017

Heart in timber

Feedback on 150x150- January 2015
The difference between pine hardwood and cypress – September 2016
Using heart-in timber – February 2017
Stump caps – March 2017
Tree of Knowledge memorial Barcaldine – April 2017
Using heart in timber correctly – April 2020

History

The two Henry Fords of housing (part 1) - August 2016
The two Henry Fords of housing (part 2) - September 2016
Trusses a brief history – October 2016
Largest timber gable truss in Australia – December 2016
Sons of Gwalia headframe restoration options – April 2017

Incised timber

Incised Timber - November 2020
Feedback on incised timber – December 2020

International

Brief trip to the Philippines – September 2016
Cocowood, is it any good? – October 2016
Rothoblass headquarters Italy using cross laminated timber – March 2017
Timber library in remote Solomon Islands – May 2017
Cyclone and earthquake resistant building in Solomons – October 2018
Spotted gum decks in Japan – May 2020
Japanese tea garden deck – July 2020
Spotted gum projects in Japan – September 2020
A striking spotted gum fence in Japan – March 2121

Joints

Tamedia building in Switzerland – May 2016
Galvanised bolts more variable than timber – June 2016
Problems looming with self drilling screws – June 2016
Tamedia building, Zurich – August 2016

Joists

Predrilling joists for screws is critical – February 2018

How not to do a timber joint – August 2018

A reminder about steel joists – November 2018

This may make steel joists work – December 2018

You can Make Steel Joists Work – January 2019

Deadly Sin No. 2 on the sunshine Coast– April 2019

Don't do silly things joining timber – October 2019

Correct detailing does matter - November 2020

Laminated timber

Don't do silly things with laminated timber – October 2019

LVL

LVL and common sense (USA deck collapse) – February 2020

Moisture Content

UTAS Want Your Moisture Content Story – December 2020

Paint and Oils

What brand paint should I use – July 2016

Lui the wood turner is a fan of Tanacoat – October 2016

Keep Your Deck Looking Good & Protected – June 2017

It is a good idea to pre-oil your deck – November 2017

Choice of paint colour is important – December 2020

Pests of timber

Identifying lyctus attack – January 2018

Pine

The difference between pine hardwood and cypress – September 2016

Never purchase treated pine on price – august 2019

Plastic Decking

See decking – Plastic

Timber, is there a better product – May 2019

Whoever thought plastic was a good idea – September 2019

Playgrounds

Kim Bowman Music – June 2017

Rethinking Robinia playground equipment – December 2018

Use of Larch in Australia – May 2019

Wishful thinking verse planning to succeed – July 2019

The perils of reverse engineering – December 2019

Most skilled spotted gum project I have ever seen – July 2020

Only trust your mother – August 2020

Playground timber – progress and request for images - November 2020

Timber in playgrounds (Broadwater project) - January 2021

Vandal resistant fasteners – February 2121

Ports North Playground – Cairns – March 2021

Pre-release editions of Timber in Playgrounds available – March 2021

Plywood

Be careful with ply fences – September 2017

New book on plywood – October 2017

Posts

Hardwood posts in concrete – February 2016

Lui the wood turner is a fan of Tanacoat (turned posts) – October 2016

Stump caps – March 2017

How not to install a post – April 2017

Something else that seemed a good idea – August 2017

Your design sins will find you out, Part 1– May 2018

Your design sins will find you out, Part 1– June 2018

Deadly Sin No 6 at Jimna Fire Tower – March 2019

A lesson from the recent bushfires – January 2010

Feedback on a lesson from recent bushfires – February 2020

The drought uncovers some deadly sins – March 2020

Projects

Tamedia building, Zurich – August 2016

A striking spotted gum fence in Japan – March 2021

Waaje Fire Tower Refurbishment – April 2021

Recycled timber

Recycled timber – Political Correctness – April 2016

Is recycled timber seasoned – October 2017

A good use of recycled timber – February 2020

Seats

This seat suits all age groups– April 2019

Shelters

The perils of reverse engineering – December 2019

Sleepers

A reminder about sleepers – March 2016

Concrete or timber sleepers – July 2016

A decent garden wall – March 2017

Jack has a rant about dodgy treatment – May 2017

Guide to Timber Garden Retaining walls – November 2017

Should have used concrete not timber – August 2019

Slip resistance

Putting form before function – June 2019

Standards

Standards you can drive a bus through – March 2015

Feedback on deficient standards – June 2015

Forest red gum – something I just noticed – August 2015

Revised standard AS/NZS 1170.2 released - August 2016
A quick look at some common species – October 2020
A Rose by any Other Name Might be Lemon (species names) – April 2021

Sundry

Inspect research Facilities – June 2015
Know a decent door supplier – July 2019
I found a decent door supplier – August 2019
A fair question about purchasing on price – November 2019
A Specification tool that is desperately needed – September 2020
Is spotted gum the cure for covid?(piggery slats) – March 2021

Timber Construction

Where is Timber Construction headed - May 2015
World's largest timber structure – March 2016
Large Timber structures – April 2016 special edition
Large Timber structures follow up – April 2016
Non-durable timber has lasted more than 100 years – May 2016
They are not using shipping containers, are they? – August 2016
Largest timber gable truss in Australia – December 2016
Salt storage shed East Windsor (USA) using shearplates – February 2017
The age of the plyscrapper – March 2018
Protect your top surface – May 2018
Another one of my follies – October 2020

Timber Queensland

Report on Feb 2016 Seminar – February 2016

Timber Research

The state of Timber research in Australia – May 2016
The state of Timber research in Australia – June 2016
The state of Timber research in Australia – July 2016
National Centre for Timber durability – November 2018

Timber Structures

World's largest timber structure – March 2016
Large Timber structures – April 2016 special edition
Large Timber structures followup – April 2016
Non durable timber has lasted more than 100 years – May 2016

Treatment

Decay in treated pine – December 2015
Decay in treated pine – January 2016
Why so hard to do the right thing - – January 2016
Jack has a rant about dodgy treatment – May 2017
When is H3 not H3? May 2017
A reminder about pine – July 2017
Cairns Regional Council sets the standard for preservation – September 2017
How to confirm correct treatment has been achieved – December 2017
Timber treatments do not repel insects – February 2018

Timber, is there a better product – May 2019
Guide for exercising due diligence with treated timber – November 2019
LVL and common sense – February 2020
Another one of my follies (Bell tower Dalby) – November 2020
Update to new timber preservation guide for free – January 2021

Unclassifiable

A mortgage broker that helped us – February 2016
How to get people to specify your product – February 2016
What do you do with a good idea – February 2016
An accountant that really helped us – May 2016
Sons of Gwalia headframe restoration options – April 2017
Book on the history of saws – February 2017
A treat for wood lovers and railway buffs – September 2020
Is spotted gum the cure for covid? (piggery slats) – March 2021

Verandahs

See Decks Domestic

Wood Solutions

New guide on mid rise developments released – October 2016
Span chart software – February 2017
Guide to Timber Garden Retaining walls – November 2017
New publication on slip resistance – December 2018
Guide to Wood Construction Systems – January 2019

Wood Encouragement Policy

A wood encouragement policy is a mixed blessing – August 2017
A wood encouragement policy, what is needed– August 2017