Timber Newsletter Index

150x150

Feedback on 150x150 - <u>January 2015</u> The drought uncovers some deadly sins – <u>March 2020</u> Which hardwood grading standard should I use – <u>April 2020</u> 150x150 kiln deied is not available – <u>May 2024</u>

3D Printing

Introduction to 3D printing – February 2015

50 mm joists

A reminder - <u>February 2015</u> Deadly Sin No. 2 on the sunshine Coast- <u>April 2019</u> Stagger your screw line - <u>July 2019</u> Correct detailing does matter - <u>November 2020</u>

Battens

Simple but stunning use of battens – <u>June 2019</u> What has a Big Mac and cladding have in common – <u>December 2019</u> Fastener end distances – <u>November 2023</u> Don't span your battens too far – <u>February 2024</u>

Boardwalks

Sacred site Boardwalks – <u>April 2015</u> Why do I bother – <u>June 2015</u> The Customer isn't always right – <u>November 2017</u> Lessons from a 30-year-old boardwalk – <u>December 2017</u> A boardwalk that planned to succeed– <u>March 2019</u> Please explain – <u>December 2019</u> Correct detailing does matter - <u>November 2020</u> Galvanised fasteners can be a Recipe for Disaster – <u>November 2021</u> We can be too clever (flood resilience) – <u>March 2022</u>

Bollards

Bollards – Let the buyer beware – <u>October 2015</u> Canberra bollards- <u>January 2015</u> Same plans but two different products –<u>December 2015</u> Timber bollards that have not aged gracefully – <u>May 2015</u> Attractive project using eclipse bollards – <u>September 2018</u> FWPA bollard guide – <u>October 2018</u> Don't specify bollards till you read this guide – <u>November 2018</u> Spreading the word in Canberra – <u>May 2019</u> How deep do bollards have to be in the ground – <u>October 2019</u> New CPD course on bollards - <u>March 2023</u> Why do we do things that are just plain wrong – <u>April 2023</u> Plastic or timber bollards, which is better? – <u>October 2023</u>

Books

Architectural Timber Batten Book completed – August 2015 Baptist History - February 2015 Fence images sought – September 2015 Help needed for architectural battens – May 2015 Images sought for footbridge book – August 2015 New book being written (Architectural Timber Battens) - June 2015 New publication finalised – October 2015, – February 2016 New book on joints being written – May 2016 Contribution to French book on tropical timber - June 2016 New book on timber joints - March 2017 New guide, External Timber Furniture – September 2018 A treat for wood lovers and railway buffs – September 2020 Pre-release editions of Timber in Playgrounds available – March 2021 Why you need Bootle's Wood in Australia - July 2022 Guide to timber handrail released – December 2022 Started new guide to timber steps - March 2023 Restoring a bridge for 1/10th the cost of concrete – April 2023 You need the industry "Bible" - July 2023

Bridges

Bridge inspection course - January 2015 Log Footbridges – April 2015 Large timber structures – April 2015 special edition Paint finish for external structures – June 2015 Wisdom of high design loads - May 2015 New publication being finalised – September 2015 What does a London bus have in common with my trusses?- December 2015 Large Timber structures – April 2016 special edition Covered bridges and the birth of American engineering-November 2016 Mareeba Shire turns to timber bridges over concrete -August 2017 You can build an Oscar worthy bridge – January 2018 Economic and speedy bridge replacement – July 2018 Covered bridges really work – April 2019 Pre-war but which war (40m timber bridge) January 2020 Krause bridge, a lesson in longevity - May 2020 The capabilities of external gluelam – August 2020 Another timber bridge to replace steel in Canada – October 2020 Iconic timber bridge restored (Brunswick Heads) – December 2020 Covered bridge restoration – February 2021 An Interesting handrail from the UK (sloping handrails) – July 2021 A Not so interesting handrail from Australia (poorly done)- July 2021 Poor Timber Design Needed a Fast Repair (laminated beam) – August 2021 35 metre span timber bridge in Canada – February 2022 A problematic timber design – August 2022 Mathematical bridge in Cambridge - May 2024

Buildings

Another great project from architects of Arcadia – <u>June 2020</u> Another one of my follies – <u>October 2020</u> Inspecting the world's largest timber structure – <u>January 2024</u>

Case Histories - Bad

Dangerous Canberra Deck - <u>January 2015</u> Dangerous Canberra deck finally made safe – <u>January 2017</u> Why do I bother (Re boardwalk) - <u>June 2015</u> Timber bollards that have not aged gracefully – <u>May 2015</u> Problematic timber bridge design – <u>August 2022</u> Step case history from step guide – <u>May 2023</u> A creative footing solution – <u>February 2024</u>

Case Histories - Good

Largest timber church in Australia – June 2016 Salt storage shed East Windsor (USA) using shearplates – February 2017 A decent garden wall – March 2017 Rothoblass headquarters Italy using cross laminated timber – March 2017 Tree of Knowledge memorial Barcaldine – April 2017 Mareeba Shire turns to timber bridges over concrete -August 2017 Kurata Co in Japan excels with spotted gum – April 2018 An early boardwalk revisited (Toohey Forest) – May 2018 Another great structure at Toohey Forest Park, Part 1– June 2018 Another great structure at Toohey Forest Park, Part 2- July 2018 Are you purchasing for durability (Brisbane Botanic Garden) – October 2018 Another one of my follies (bell tower Dalby) - November 2020 Domestic deck at The Gap - February 2021 Ports North Playground – Cairns – March 2021 Spotted gum seats in Budapest – May 2021 Queenslander houses – May 2021 Deck replacement – Gold Coast – October 2021 Two bell towers compared (Dalby and Charters Towers) – November 2021 We can be too clever (flood resilience) - March 2022 Spotted gum viewing deck in Japan – June 2022 Something good in Canberra (pergola) – <u>August 2022</u> Refurbished deck at Samford – December 2022 All Hallows school deck – May 2023 Uluru drone show boardwalk and deck – June 2023 Amazing spotted gum deck in Japan – August 2023 Handrail on refurbished footbridge – October 2023 Sunpu's workshop, Takumijuku (Japan) – December 2023 Case History – Mayes Canal Boardwalk – April 2024

Cladding

What have a Big Mac and cladding have in common – <u>December 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u> Timber cladding in multi-story buildings – September 2020

Cocowood

Cocowood, is it any good? – October 2016

Connections

World's largest timber structure – <u>March 2016</u> Salt storage shed East Windsor (USA) using shearplates – <u>February 2017</u>

Consultancy Services

Expert witness – <u>November 2015</u> Ted is speaking on battens for Timber Queensland – <u>January 2016</u> Gold Coast City Council builds an outstanding deck – <u>July 2017</u> Consultancy services through BCRC – <u>August 2017</u> The importance of Timber Grading – <u>December 2017</u> Footbridge inspections – <u>August 2018</u> Grading timber in a Venetian palace – <u>November 2018</u> Why you need to engage a timber consultant even if it's not me – <u>November 2019</u>

Cypress

The difference between pine hardwood and cypress – September 2016

Deck Collapses

Another deck collapse – <u>December 2017</u> Another deck fatality before the coroner – <u>June 2020</u>

Decks – Commercial

Deckwood – new manufacturing arrangements – January 2016 Ted has finally found something more durable than Deckwood – November 2015 Width to thickness ratio - - November 2016 How long will a timber deck last – March 2017 Joining decks on commercial decking – June 2017 Choosing timber by colour - July 2017 Gold Coast City Council builds an outstanding deck – July 2017 What decking profile us that - July 2017 Should decks be load limited – November 2017 It is a good idea to pre-oil your deck – <u>November 2017</u> Avoiding trip hazards in decking – April 2020 Are your decks self-cleaning – April 2020 Why you don't use dressed face decking externally - August 2018 Putting form before function – June 2019 Spotted gum decks in Japan – May 2020 This is why you do things correctly – July 2020 Japanese tea garden deck – July 2020 Why don't we check – August 2020 Deck replacement – Gold Coast – October 2021 What decking oil should I use – May 2022 Deckwood available for vehicle decking – June 2022 Amazing spotted gum deck in Japan – August 2023 Case History – Mayes Canal Boardwalk – April 2024

Decks - Domestic

How to ensure correct verandah joist life – August 2015 Nail or screw domestic decking – April 2015 Some basics – November 2015 How to Protect and keep your deck looking good – June 2017 Choosing timber by colour - July 2017 Should decks be load limited – November 2017 It is a good idea to pre-oil your deck – November 2017 Why you don't use dressed face decking externally – August 2018 A Dear Lord Give my strength moment – January 2019 Updated Timber Queensland Decking Guides – September 2019 LVL and common sense (USA deck collapse) – February 2020 Spotted gum decks in Japan – May 2020 Another deck fatality before the coroner – June 2020 Beware F17 KD specification – September 2021 What decking oil should I use – May 2022 Refurbished deck at Samford (LifePlus) – December 2022 All hallows School Lifeplus – May 2023 Timber decks close to the ground – December 2023 Sometimes timber is a poor choice – April 2024

Decks - Plastic

Plastic decking with termites – <u>September 2016</u> It seemed a good idea at the time – <u>August 2017</u> Another failed plastic deck – <u>April 2018</u> Timber, is there a better product – <u>May 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u>

Durability

Thermally modified timber - <u>January 2015</u> Designing for the local climate – <u>November 2015</u> Non durable timber has lasted more than 100 years – <u>May 2016</u> Deadly Sin No. 7, Getting Durability ratings Right – <u>February 2019</u> Oils ain't oils and wood ain't wood – <u>February 2019</u> National centre for timber durability – <u>June 2020</u> This is why I disapprove of using Oregon pine externally – <u>July 2020</u> A quick look at some common species – <u>October 2020</u> Another one of my follies (Kangaroo Point) – <u>October 2020</u> Another one of my follies (Bell tower Dalby) – <u>November 2020</u> Beware F17 KD specification – <u>September 2021</u> Two bell towers compared (Dalby and Charters Towers) – <u>November 2021</u> We can be too clever (flood resilience) – <u>March 2022</u> Is Oregon durable – <u>May 2023</u> Care needed with kwila/merbau – <u>November 2023</u>

Engineered Timber

Using laminated beams externally – <u>September 2015</u> Using LVL beams externally – <u>September 2015</u> Rothoblass headquarters Italy using cross laminated timber – <u>March 2017</u> Timber library in remote Solomon Islands – <u>May 2017</u> Mareeba Shire turns to timber bridges over concrete -<u>August 2017</u> Be careful choosing your species – <u>October 2017</u>

Fences – Domestic

Fence images sought – <u>September 2015</u>, <u>October 2015</u> Timber fence book finalised – <u>January 2016</u> Everything fencing – <u>April 2016</u> Be careful with ply fences – <u>September 2017</u> Be careful choosing your species – <u>October 2017</u> A striking spotted gum fence in Japan – <u>March 2021</u> How not to do a fence – <u>April 2022</u> Horse fencing – <u>November 2023</u>

Fasteners

Nail or screw domestic decking – April 2015 When to use stainless bolts and brackets – July 2015 Galvanised bolts more variable than timber – June 2016 Problems looming with self drilling screws – June 2016 More on galvanised bolts - July 2016 More on galvanised bolts – August 2016 More on galvanised bolts - September 2016 Choosing the correct decking fastener part 1 – November 2016 Choosing the correct decking fastener part 2 – December 2016 Choosing the correct decking fastener part 3 – January 2017 Corroding galvanised joist hangers – November 2016 Tube nuts – December 2016 Salt storage shed East Windsor (USA) using shearplates – February 2017 A Dear Lord Give my strength moment – January 2019 Stagger your screw line – July 2019 Why don't we check – <u>August 2020</u> Vandal resistant fasteners – February 2021 Tell me how to detail it Correctly (steel corroding at stainless bolt) – April 2021 Tell me how to detail it Correctly replies (steel corroding at stainless bolt) – June 2021 Staying one jump ahead of the idiots (need for special nuts) – June 2021 Galvanised fasteners can be a Recipe for Disaster – November 2021 End and edge clearances of bolts – March 2022 Fastening domestic decking to steel joists – February 2023 Recommended screw for fixing Deckwood to steel – August 2023 Fastener end distances – November 2023

Flooring

A real-life ghost story – <u>March 2015</u> Controlling the gaps in T&G flooring – <u>March 2018</u> When is kiln dried not kiln dried – <u>January 2019</u> A reminder about narrow floorboards – <u>September 2019</u> Queenslander houses – <u>May 2021</u> Using T&G flooring as decking – <u>February 2023</u>

Finishing

A real-life ghost story – <u>March 2015</u> Paint finish for external structures – <u>June 2015</u> Keep Your Deck Looking Good & Protected – <u>June 2017</u> It is a good idea to pre-oil your deck – <u>November 2017</u> Don't do silly things with timber – <u>November 2019</u> Choice of paint colour is important – <u>December 2020</u> Tell me how to detail it correctly replies (painted steel corroding at stainless bolt) – <u>June 2021</u> What decking oil should I use – <u>May 2022</u>

Fire

Fire retardant coatings code of practice released – <u>June 2018</u> A lesson from the recent bushfires (CCA and fire) – <u>January 2020</u> Feedback on a lesson from recent bushfires – <u>February 2020</u>

Furniture

Be careful choosing your species – <u>October 2017</u> Writing a book on external furniture – <u>November 2017</u> External timber furniture, all you need to know – <u>October 2018</u> When a one-off has to be right first time – <u>June 2024</u>

Grading

A reminder about sleepers – <u>March 2016</u> How to measure end splits – <u>March 2016</u> Limitations of visual grading – <u>January 2018</u> Don't specify timber by F grades – <u>August 2018</u> Which hardwood grading standard should I use – <u>April 2020</u> A philosophical question prompted by Kortney and Dave – <u>January 2021</u> Losing confidence in timber is so unnecessary – <u>September 2021</u> Beware F17 KD specification – <u>September 2021</u> Deck replacement – Gold Coast – <u>October 2021</u> How not to do a fence – <u>April 2022</u> New hardwood requires care in its specification – <u>June 2022</u> Guide to timber handrail released – <u>December 2022</u> Never specify sleepers – <u>June 2023</u> A broken heart in one so young – <u>August 2023</u>

Handrail

Detailing a commercial handrail – <u>June 2019</u> An Interesting handrail from the UK (sloping handrails) – <u>July 2021</u> A Not so interesting handrail from Australia (poorly done)– <u>July 2021</u> New CPD Course on handrail – <u>August 2021</u> Losing confidence in timber is so unnecessary – <u>September 2021</u> Fixing handrails – October 2021 Correct use of LOSP Treated Handrail - January 2022 Do end sealants actually work – February 2022 A suggested handrail bracket – February 2022 Specification for commercial handrail – July 2022 Guide to timber handrail released – December 2022 Handrail on refurbished footbridge – October 2023 Why is this handrail 6.4m long? - March 2024 A truly Dreadful Handrail – June 2024

Hardware

Fencing brackets – <u>February 2016</u> Corroding galvanised joist hangers – <u>November 2016</u> Salt storage shed East Windsor (USA) using shearplates – <u>February 2017</u> Stump caps – <u>March 2017</u>

Heart in timber

Feedback on 150x150- <u>January 2015</u> The difference between pine hardwood and cypress – <u>September 2016</u> Using heart-in timber – <u>February 2017</u> Stump caps – <u>March 2017</u> Tree of Knowledge memorial Barcaldine – <u>April 2017</u> Using heart in timber correctly – <u>April 2020</u> Losing confidence in timber is so unnecessary – <u>September 2021</u>

History

The two Henry Fords of housing (part 1) - <u>August 2016</u> The two Henry Fords of housing (part 2) – <u>September 2016</u> Trusses a brief history – <u>October 2016</u> Largest timber gable truss in Australia – <u>December 2016</u> Sons of Gwalia headframe restoration options – <u>April 2017</u>

Incised timber

Incised Timber - <u>November 2020</u> Feedback on incised timber – <u>December 2020</u> Feedback on Recognising well treated sleepers – <u>February 2024</u>

International

Brief trip to the Philippines – <u>September 2016</u> Cocowood, is it any good? – <u>October 2016</u> Rothoblass headquarters Italy using cross laminated timber – <u>March 2017</u> Timber library in remote Solomon Islands – <u>May 2017</u> Cyclone and earthquake resistant building in Solomons – <u>October 2018</u> Spotted gum decks in Japan – <u>May 2020</u> Japanese tea garden deck – <u>July 2020</u> Spotted gum projects in Japan – <u>September 2020</u> Spotted gum viewing deck in Japan – <u>June 2022</u> Amazing spotted gum deck in Japan – <u>August 2023</u>

Joints

Tamedia building in Switzerland – <u>May 2016</u> Galvanised bolts more variable than timber – <u>June 2016</u> Problems looming with self-drilling screws – <u>June 2016</u> Tamedia building, Zurich – <u>August 2016</u>

Joists

Predrilling joists for screws is critical – <u>February 2018</u> How not to do a timber joint – <u>August 2018</u> A reminder about steel joists – <u>November 2018</u> This may make steel joists work – <u>December 2018</u> You can Make Steel Joists Work – <u>January 2019</u> Deadly Sin No. 2 on the sunshine Coast– <u>April 2019</u> Don't do silly things joining timber – <u>October 2019</u> Correct detailing does matter - <u>November 2020</u> Beware F17 KD specification – <u>September 2021</u> Fastening domestic decking to steel joists – February 2023

Laminated timber

Pre-war but which war (40m laminated timber bridge) <u>January 2020</u> Don't do silly things with laminated timber – <u>October 2019</u> Poor Timber Design Needed a Fast Repair (laminated beam bridge) – <u>August 2021</u> Repairing Broken beams – <u>April 2024</u>

LVL

LVL and common sense (USA deck collapse) – February 2020

Moisture Content

UTAS Want Your Moisture Content Story – December 2020

Paint and Oils

What brand paint should I use – <u>July 2016</u> Lui the wood turner is a fan of Tanacoat – <u>October 2016</u> Keep Your Deck Looking Good & Protected – <u>June 2017</u> It is a good idea to pre-oil your deck – <u>November 2017</u> Choice of paint colour is important – <u>December 2020</u> What paint brand should I specify – <u>April 2022</u> What decking oil should I use – <u>May 2022</u> Tanacoat or Tanacare – <u>February 2024</u>

Pests of timber

Identifying lyctus attack – January 2018

Pine

The difference between pine hardwood and cypress – <u>September 2016</u> Never purchase treated pine on price – <u>August 2019</u> Is Oregon durable – <u>May 2023</u>

Plastic Decking

See decking – Plastic Timber, is there a better product – <u>May 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u>

Playgrounds

Kim Bowman Music – June 2017 Rethinking Robinia playground equipment – December 2018 Use of Larch in Australia – May 2019 Wishful thinking verse planning to succeed – July 2019 The perils of reverse engineering – December 2019 Most skilled spotted gum project I have ever seen – July 2020 Only trust your mother – August 2020 Playground timber – progress and request for images - November 2020 Timber in playgrounds (Broadwater project) - January 2021 Vandal resistant fasteners – February 2021 Ports North Playground – Cairns – March 2021 Pre-release editions of Timber in Playgrounds available – March 2021 Text finalised for Timber in Playground guide – June 2021 Example of why you need the playground guide – January 2022 Bradbury Park Playspace – July 2023

Plywood

Be careful with ply fences – <u>September 2017</u> New book on plywood – <u>October 2017</u>

Posts

Hardwood posts in concrete - February 2016 Lui the wood turner is a fan of Tanacoat (turned posts) – October 2016 Stump caps - March 2017 How not to install a post – April 2017 Something else that seemed a good idea – <u>August 2017</u> Your design sins will find you out, Part 1- May 2018 Your design sins will find you out, Part 1- June 2018 Deadly Sin No 6 at Jimna Fire Tower – March 2019 A lesson from the recent bushfires – January 2020 Feedback on a lesson from recent bushfires – February 2020 The drought uncovers some deadly sins – March 2020 Lay your design sins at the foot of the cross (revisited) - June 2021 Basic error with post supports - January 2022 Why do we do things that are just plain wrong – April 2023 Guidelines for installing gal posts in concrete – April 2023 Groundline special edition – September 2023 Post size requirements – September 2023 Timber house stumps – September 2023 Lay your design sins at the foot of the cross (revisited again) – September 2023 Steel posts – September 2023 A creative footing solution – February 2024 H5 treated pine without CCA – April 2024

Projects

Tamedia building, Zurich – <u>August 2016</u> A striking spotted gum fence in Japan – <u>March 2021</u> Waaje Fire Tower Refurbishment – <u>April 2021</u>

Recycled timber

Recycled timber – Political Correctness – <u>April 2016</u> Is recycled timber seasoned – <u>October 2017</u> A good use of recycled timber – <u>February 2020</u>

Sapwood

Considering sapwood in your design - December 2021

Seats

This seat suits all age groups- <u>April 2019</u> Spotted gum seats in Budapest - <u>May 2021</u>

Shelters

The perils of reverse engineering – <u>December 2019</u> Shelter shed design service – <u>August 2021</u>

Sleepers

A reminder about sleepers – <u>March 2016</u> Concrete or timber sleepers – <u>July 2016</u> A decent garden wall – <u>March 2017</u> Jack has a rant about dodgy treatment – <u>May 2017</u> Guide to Timber Garden Retaining walls – <u>November 2017</u> Should have used concrete not timber – <u>August 2019</u> Never specify sleepers – <u>June 2023</u> Recognising correctly treated sleepers – <u>January 2024</u> Feedback on Recognising well treated sleepers – <u>February 2024</u>

Slip resistance

Putting form before function – <u>June 2019</u>

Standards

Standards you can drive a bus through – <u>March 2015</u> Feedback on deficient standards – <u>June 2015</u> Forest red gum – something I just noticed – <u>August 2015</u> Revised standard AS/NZS 1170.2 released - <u>August 2016</u> A quick look at some common species – <u>October 2020</u> A Rose by any Other Name Might be Lemon (species names) – <u>April 2021</u>

Steps

Specification for step treads – <u>July 2022</u> Case history (bad) from step guide – <u>May 2023</u>

Sundry

Inspect research Facilities – <u>June 2015</u> Know a decent door supplier – <u>July 2019</u> I found a decent door supplier – <u>August 2019</u> A fair question about purchasing on price – <u>November 2019</u> A Specification tool that is desperately needed – <u>September 2020</u> Is spotted gum the cure for covid? (piggery slats) – <u>March 2021</u> Calculating the weight of timber – <u>August 2021</u> Horse fencing– <u>November 2023</u>

Timber Construction

Where is Timber Construction headed - <u>May 2015</u> World's largest timber structure – <u>March 2016</u> Large Timber structures – <u>April 2016</u> special edition Large Timber structures follow up – <u>April 2016</u> Non-durable timber has lasted more than 100 years – <u>May 2016</u> They are not using shipping containers, are they? – <u>August 2016</u> Largest timber gable truss in Australia – <u>December 2016</u> Salt storage shed East Windsor (USA) using shearplates – <u>February 2017</u> The age of the plyscraper – <u>March 2018</u> Protect your top surface – <u>May 2018</u> Another one of my follies – <u>October 2020</u>

Timber Queensland

Report on Feb 2016 Seminar – February 2016

Timber Research

The state of Timber research in Australia – <u>May 2016</u> The state of Timber research in Australia – <u>June 2016</u> The state of Timber research in Australia – <u>July 2016</u> National Centre for Timber durability – <u>November 2018</u>

Timber Structures

World's largest timber structure – <u>March 2016</u> Large Timber structures – <u>April 2016</u> special edition Large Timber structures follow up – <u>April 2016</u> Non durable timber has lasted more than 100 years – <u>May 2016</u>

Treatment

Decay in treated pine – <u>December 2015</u> Decay in treated pine – <u>January 2016</u> Why so hard to do the right thing - – <u>January 2016</u> Jack has a rant about dodgy treatment – <u>May 2017</u> When is H3 not H3? <u>May 2017</u> A reminder about pine – <u>July 2017</u> Cairns Regional Council sets the standard for preservation – <u>September 2017</u> How to confirm correct treatment has been achieved – <u>December 2017</u> Timber treatments do not repel insects – <u>February 2018</u> Timber, is there a better product – <u>May 2019</u> Guide for exercising due diligence with treated timber – <u>November 2019</u> Lesson from a recent bushfire (CCA and fire) – <u>January 2020</u> LVL and common sense – <u>February 2020</u> Another one of my follies (Bell tower Dalby) – <u>November 2020</u> Update to new timber preservation guide for free – <u>January 2021</u> Considering sapwood in your design - <u>December 2021</u> Correct use of LOSP Treated Handrail - <u>January 2022</u> What do the numbers on a treatment tag mean? – <u>January 2024</u> H5 treated pine without CCA – <u>April 2024</u>

Unclasifiable

A mortgage broker that helped us – February 2016 How to get people to specify your product – February 2016 What do you do with a good idea – February 2016 An accountant that really helped us – May 2016 Sons of Gwalia headframe restoration options – April 2017 Book on the history of saws – February 2017 A treat for wood lovers and railway buffs – September 2020 Is spotted gum the cure for covid? (piggery slats) – March 2021 The Olympics of materials – July 2021 Design decision making matrix is needed – August 2022 Glad to help a young engineer with her master's degree - March 2023 Something for lovers of concrete - March 2023

Verandahs See Decks Domestic

Wood Solutions

New guide on mid rise developments released – <u>October 2016</u> Span chart software – <u>February 2017</u> Guide to Timber Garden Retaining walls – <u>November 2017</u> New publication on slip resistance – <u>December 2018</u> Guide to Wood Construction Systems – <u>January 2019</u>

Wood Encouragement Policy

A wood encouragement policy is a mixed blessing – <u>August 2017</u> A wood encouragement policy, what is needed – <u>August 2017</u>